

Milling Machine Fundamentals

Wayne Staats, UW-Madison FSAE

Overview

- Safety
- Shop Etiquette
- Basic Terminology
- Before Machining
- Indicating
- Calculating Feeds and Speeds
- Machining
- Maintenance

Safety

- Respect the machines
- Common Sense
 - Wear safety glasses
 - Avoid loose clothing
 - Restrain long hair
 - Never wear gloves
 - Never wear shorts or sandals
 - Stay alert

Shop Etiquette


- Vehicle Projects Machine Shop
 - Clean up / Vacuum
 - Oil machinery
 - Leave notes when necessary
 - Report broken tools

Shop Etiquette

- COE Shop
 - ALWAYS leave machines cleaner!
 - Ask for help, if needed
 - Come prepared
 - Tooling list
 - Plan of action
 - Dimensioned drawings
 - Check out CNC machines in advance



Basic Terminology

- Mills in the shop – “vertical knee mills” (aka Bridgeports)



Basic Terminology

- Coordinates
 - With respect to workpiece



- Digital Readout (DRO)
 - Displays coordinates
 - Absolute or incremental, standard or metric



Basic Terminology


- Feeds and Speeds (F/S)
 - Spindle Speed (speed) [rpm]: Speed (rpm) that tool rotates
 - Feed Rate (feed) [in/tooth or in/rev]: Amount of lateral movement occurs during each rotation of the tool
 - Surface Speed [sfpm – surface feet per minute]: How fast edge of tool moves with respect to workpiece

Basic Terminology

- Cutting


- Conventional (up) milling

- For roughing cuts, or if workpiece cannot be positioned securely
- On CNC mill, "tool right"



- Climb (down) milling

- For finishing cuts
- On CNC mill, "tool left"



Basic Terminology

- Tooling

- End mills

- Roughing End Mill (aka Rougher)

- Finishing End Mill (aka Finisher)

- Ball End Mill


- For internal radii

- Corner Rounding End Mill

- For external radii

- Chamfer Mill

- And, many, many more



Basic Terminology

- Tooling

- Fly cutter



Basic Terminology

- Tooling

- Center Drill



- Keeps holes accurately positioned

- Twist Drill



- Reamer



- Usually pre-drill to 1/64th under

- Adjustable Boring Bar

Basic Terminology

- Tooling

- Collets

- End mill goes into collet, and then into spindle

- Jacobs Chuck

- Mainly for drill bits
- Usually not as accurate as a collet

- Mill wrench




Basic Terminology

- Indicating

- Dial indicator

- Test indicator

- Edge finder



Pointed edge finder – for locating a hole

Basic Terminology





- Fixturing

- Vise

- Clamping Kit

- T-slot nuts
- Flange nuts
- Coupling nuts
- Step blocks
- Step clamps

- Parallel Bars







Basic Terminology

- Fixturing

- V-blocks

- Collet blocks


- Rotary table



Before Machining

- Trammig the head
 - X-axis

Locking screws




Before Machining

- Trammig the head
 - Y-axis

Adjustment screw

Locking screws




Before Machining

- Trammig the head

Trammig fixture

Dial indicator




Before Machining

- Trammig the head

Trammig fixture

Dial indicator




Before Machining

- Trammig the head
 1. Preload dial indicator against table by raising knee
 2. Check height on either end of circle defined by fixture (put mill in neutral)
 3. Loosen locking screws (not completely)
 4. Make adjustment (beware of backlash and split the difference)



Before Machining

- Squaring the vise
 - Similar to trammig the head
 - Try to avoid overcorrection: approach the goal slowly



Dial (test) indicator

Smooth vise surface




Before Machining

- Squaring the vise
 1. Start at one end and zero indicator
 2. Move to other end, read indicator
 3. Loosen vise clamping nuts slightly
 4. Tap with mill wrench (split the difference)
 5. Tighten vise clamping nuts and repeat procedure



Indicating


- Using an edge finder
 - Useful for locating a straight edge
 - Remember to compensate for tool radius



Edge finder

Stock

Vise



Indicating

- Using an edge finder



Indicating

- Using an edge finder
 1. Insert edge finder/collet into spindle
 2. Turn on mill (avoid high speeds – stick with 1600 or below)
 3. Approach edge of part
 4. When edge finder is visibly concentric, you have found the edge
 5. If edge finder makes noise and comes off center, you've gone too far
 6. Remember – You must compensate for the tool radius when setting the DRO!

Indicating

- Using a dial (test) indicator


– Useful for finding the axis of a cylindrical surface

Test indicator

Stock

Vise

V-block



Indicating

- Using a dial (test) indicator
 1. Move stock so that axis is almost directly under the spindle
 2. Ensure that indicator never loses contact with stock or bottoms out (this involves adjusting the indicator screws)
 3. Put mill in neutral and rotate spindle around part
 4. Move x and y axes so that indicator has consistent reading around part

Calculating Feeds and Speeds

- Machinery's Handbook
 - Can use formulas from here to calculate proper spindle speed
- Chart
- Use this if you don't feel like doing any math
- Calculate feed (for CNCs) using formulas from Machinery's Handbook
- Proper F/S makes a big difference!



Calculating Feeds and Speeds

| Sp. Sfm | Revolutions per minute | | | | | | | | | | | | | | | | |
|---------|------------------------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|
| | 40 | 50 | 60 | 70 | 80 | 90 | 100 | 120 | 140 | 160 | 180 | 200 | 225 | 250 | 275 | 300 | 325 |
| 1/4 | 611 | 764 | 917 | 1070 | 1222 | 1376 | 1528 | 1684 | 2139 | 2445 | 2750 | 3056 | 3438 | 3820 | 4202 | 4586 | 4966 |
| 5/16 | 489 | 611 | 733 | 856 | 978 | 1100 | 1222 | 1466 | 1711 | 1955 | 2200 | 2444 | 2750 | 3056 | 3362 | 3667 | 3973 |
| 3/8 | 408 | 509 | 611 | 713 | 815 | 918 | 1018 | 1222 | 1426 | 1629 | 1832 | 2036 | 2239 | 2442 | 2645 | 2847 | 3050 |
| 7/16 | 348 | 437 | 524 | 611 | 699 | 786 | 874 | 1049 | 1224 | 1398 | 1573 | 1748 | 1964 | 2182 | 2401 | 2621 | 2837 |
| 1/2 | 306 | 382 | 459 | 535 | 611 | 688 | 764 | 917 | 1070 | 1222 | 1375 | 1528 | 1719 | 1910 | 2101 | 2301 | 2483 |
| 9/16 | 272 | 340 | 407 | 475 | 543 | 611 | 679 | 813 | 951 | 1088 | 1222 | 1358 | 1528 | 1698 | 1868 | 2037 | 2207 |
| 5/8 | 245 | 306 | 367 | 428 | 489 | 552 | 612 | 736 | 857 | 979 | 1102 | 1224 | 1375 | 1528 | 1681 | 1831 | 1987 |
| 11/16 | 222 | 273 | 333 | 389 | 444 | 500 | 555 | 666 | 770 | 888 | 999 | 1101 | 1250 | 1389 | 1528 | 1678 | 1826 |
| 3/4 | 203 | 254 | 306 | 357 | 408 | 458 | 509 | 610 | 711 | 813 | 914 | 1016 | 1146 | 1273 | 1401 | 1528 | 1655 |
| 13/16 | 190 | 237 | 284 | 332 | 379 | 427 | 474 | 569 | 664 | 758 | 853 | 948 | 1068 | 1175 | 1293 | 1401 | 1528 |
| 7/8 | 175 | 219 | 262 | 306 | 349 | 392 | 436 | 526 | 613 | 701 | 788 | 876 | 982 | 1091 | 1200 | 1300 | 1410 |
| 15/16 | 163 | 204 | 244 | 285 | 326 | 366 | 407 | 488 | 570 | 651 | 733 | 814 | 917 | 1019 | 1120 | 1220 | 1324 |
| 1 | 153 | 191 | 229 | 267 | 306 | 344 | 382 | 458 | 535 | 611 | 688 | 764 | 859 | 955 | 1050 | 1150 | 1241 |
| 1 1/16 | 144 | 180 | 215 | 251 | 287 | 323 | 359 | 431 | 503 | 575 | 648 | 718 | 808 | 899 | 988 | 1088 | 1188 |
| 1 1/8 | 136 | 170 | 204 | 238 | 272 | 306 | 340 | 408 | 476 | 544 | 612 | 680 | 764 | 848 | 933 | 1013 | 1103 |
| 1 3/16 | 129 | 161 | 193 | 225 | 258 | 290 | 322 | 386 | 451 | 515 | 580 | 644 | 724 | 804 | 884 | 964 | 1045 |
| 1 1/4 | 123 | 153 | 183 | 214 | 245 | 274 | 305 | 367 | 429 | 490 | 551 | 612 | 687 | 764 | 840 | 919 | 999 |
| 1 5/16 | 116 | 146 | 175 | 204 | 233 | 262 | 291 | 349 | 407 | 465 | 524 | 582 | 654 | 727 | 800 | 874 | 946 |
| 1 3/8 | 111 | 139 | 167 | 195 | 222 | 250 | 278 | 334 | 389 | 445 | 500 | 556 | 626 | 694 | 764 | 834 | 903 |
| 1 7/16 | 106 | 133 | 159 | 186 | 212 | 239 | 265 | 318 | 371 | 424 | 477 | 530 | 598 | 664 | 730 | 797 | 863 |
| 1 1/2 | 102 | 127 | 153 | 178 | 204 | 230 | 255 | 305 | 356 | 406 | 457 | 508 | 579 | 643 | 707 | 770 | 827 |
| 1 9/16 | 97.6 | 122 | 146 | 171 | 195 | 220 | 244 | 293 | 342 | 390 | 439 | 488 | 550 | 611 | 672 | 732 | 784 |
| 1 5/8 | 93.9 | 117 | 141 | 165 | 189 | 212 | 234 | 281 | 328 | 374 | 421 | 468 | 529 | 587 | 646 | 704 | 754 |
| 1 11/16 | 90.4 | 113 | 136 | 158 | 181 | 203 | 225 | 271 | 316 | 362 | 407 | 452 | 500 | 556 | 612 | 667 | 725 |
| 1 3/4 | 87.3 | 109 | 131 | 153 | 175 | 196 | 218 | 262 | 305 | 349 | 392 | 436 | 474 | 527 | 579 | 631 | 685 |
| 1 7/8 | 84.3 | 105 | 127 | 149 | 169 | 189 | 209 | 252 | 294 | 336 | 378 | 421 | 458 | 503 | 547 | 592 | 640 |
| 2 | 76.4 | 95.5 | 115 | 134 | 153 | 172 | 191 | 229 | 267 | 305 | 344 | 382 | 424 | 477 | 525 | 575 | 620 |
| 2 1/8 | 72 | 90 | 108 | 126 | 144 | 162 | 180 | 216 | 252 | 288 | 324 | 360 | 404 | 449 | 494 | 544 | 584 |
| 2 1/4 | 68 | 85.5 | 102 | 119 | 136 | 153 | 170 | 204 | 238 | 272 | 306 | 340 | 382 | 424 | 466 | 508 | 551 |
| 2 3/8 | 64.4 | 80.5 | 96.6 | 113 | 129 | 145 | 161 | 193 | 225 | 258 | 290 | 322 | 362 | 402 | 442 | 482 | 522 |
| 2 1/2 | 61.2 | 76.3 | 91.7 | 107 | 122 | 138 | 153 | 184 | 213 | 245 | 275 | 306 | 343 | 382 | 420 | 450 | 496 |
| 2 5/8 | 58 | 72.5 | 87 | 102 | 116 | 131 | 145 | 174 | 203 | 232 | 261 | 290 | 327 | 363 | 400 | 430 | 471 |
| 2 3/4 | 55.6 | 69.5 | 83.4 | 97.2 | 111 | 125 | 139 | 167 | 195 | 222 | 250 | 278 | 312 | 347 | 381 | 411 | 451 |
| 2 7/8 | 52.8 | 66 | 79.2 | 92.4 | 106 | 119 | 132 | 158 | 185 | 211 | 238 | 264 | 299 | 332 | 365 | 395 | 431 |

| Steel (rough) | Mild steel | Cast iron (medium) | Bronzes | Brass (soft) | Aluminum |
|---------------|------------|--------------------|---------|--------------|----------|
| 15 - 18 | 30-38 | 18-24 | 24-45 | 45-60 | 75-105 |
| 50 - 60 | 100-125 | 60-80 | 80-150 | 150-200 | 250-350 |


Machining

- Always lock axes for straight cuts (unless on a CNC)
- Make sure nothing is tangled in cutter
- Always know locations of stop and E-stop buttons

Maintenance


- Clean up
 - Vacuum and sweep chips
 - Limit use of air hose

Always wipe up this area (behind the worktable)



Maintenance

- Clean up



Vacuum (aka R2D2)

Maintenance

- Oil machines
 - Ways: 1-2 pumps on the way oiler
 - Spindle bearings: Fill after each use
 - Note: COE shop staff does this weekly, but it's your responsibility in the vehicle projects shop
 - DO NOT use way oil for the spindle bearings!
 - Worktable and vise: wipe down with oil after each use
 - Parts: Apply fogging oil or WD-40 to prevent corrosion


Maintenance

- Oil machines



Oil ways here (pump)

Oil spindle bearings here



Maintenance

- Oil machines



Rag

Way oil

Questions

Conclusion

- Now, make some parts and learn to use the CNC mills in the COE shop
 - Ask someone who knows, or check out the user manual
- Never be afraid to ask for help
- Experience is the best way to learn